

MATERIAL SAFETY DATA SHEET

Issued: August 6, 1992
REVISED: February 2, 2010

SECTION 1: PRODUCT INFORMATION

Product Name: Reinforcing Fabric HD
Manufacturer: GEMITE PRODUCTS INC.
Address: 1787 Drew Road, Mississauga, ON L5S 1J5
Emergency Phone: US: 888-443-6483 CANADA: 905-672-2020
Chemical Family: Polypropylene (Case Reg. # 9003-01-0)

SECTION 2: HAZARDOUS INGREDIENTS

None

SECTION 3: PHYSICAL DATA

Odour & Appearance: No Odour, Clear to opaque (white)
Vapour Pressure: N.A.
Vapour Density: N.A.
Evaporation Rate: N.A.
Boiling Point : N.A.
Melting Point : 325- 335 °F (148 – 154 °C)
Specific Gravity 0.905
Solubility in Water: Negligible

SECTION 4: FIRE & EXPLOSION DATA

Flammability: Non-flammable
Extinguishing Media: Dry chemical, foam carbon dioxide, water spray
Special Procedures: Avoid inhalation of vapours; do not enter confined fire space without full bunker gear. Cool fire exposed containers with water.
Explosion Hazards: Treat as a solid that can burn. Usually burns slowly with low smoke density and flaming drips. Can burn with high smoke density under certain conditions.

SECTION 5: REACTIVITY DATA

Conditions Contributing to Instability: Stable
Incompatibility: Strong Oxidizing Agents
Hazardous Polymerization: Will not occur
Reactivity Conditions: N.A.

SECTION 6: TOXICOLOGICAL PROPERTIES

Route of Entry: Eyes, Mouth, Skin
Skin Contact: Reddening of skin upon repeated or prolonged contact
Eye Contact: Slight irritation with direct contact
Inhalation: Overexposure from spray mist may irritate upper respiratory tract
Ingestion: No adverse effects
Effects of Chronic Exposure: N .A
TLV: N .A.

SECTION 7: PREVENTATIVE MEASURES

Protective Equipment

- **Gloves Type:** Impervious gloves
Respiratory Type: Respiratory protection is required when sanding or grinding the finished product
Eye Type: N.A.
- **Clothing Type:** N.A.
Engineering Controls: N.A.

Leak/ Spill: Wash down with water
Waste Disposal: Same as paint.
Handling Procedures & Equipment: Avoid skin and eye contact
Storage: Keep containers tightly closed when not in use.

SECTION 8	FIRST AID MEASURES
------------------	---------------------------

Eye Contact: Flush eyes with water for at least 15 minutes holding eyelids open. Prompt action is essential for eye contact. Obtain medical attention.
Skin Contact: Wash exposed areas with soap and water.
Inhalation: Move person to fresh air.
Ingestion: Unless unconscious or convulsing, dilute material with water or milk. Do not induce vomiting. See Physician.

N.A.: Not applicable